



Sneltoetsen voor Business Center 5.0

CTRL A = Select All	CTRL SHIFT A = Create Alignment
CTRL B = Break	CTRL SHIFT C = Change Elevation
CTRL C = Copy	CTRL SHIFT E = Restore region
CTRL D = Delete	CTRL SHIFT F = Offset Line
CTRL F = Filter Line Markings	CTRL SHIFT L = Label Alignment
CTRL J = Join Lines	CTRL SHIFTY O = Options
CTRL L = Layer Manager	CTRL SHIFT S = Create Surface
CTRL M = Move	CTRL SHIFT R = Restore All
CTRL N = New Project	CTRL SHIFT T = Trim / Extend Lines
CTRL O = Open Project	F1 = Help
CTRL P = Print	F4 = Compute Project
CTRL Q = Keep Out	F5 = Rectangle Select
CTRL R = Relayer	F6 = Polygon Select
CTRL S = Save Project	F7 = Left Mouse Pan
CTRL T = Create Point Cloud Region	F8 = Left Mouse Zoom
CTRL W = Keep In	F9 = Project Explorer
CTRL X = Cross Section Editor	F10 = Device Pane
CTRL Y = Redo	F11 = Properties
CTRL Z = Undo	F12 = Command Pane